



Zakazka:2256



Test.: 2




14:39:03




Datum: 22.04.2010



Maier Karel
 Pod vrchem 21
 140 00 Praha 4
 Tel. 226 326 662



SPZ : 3A0 6589
 Znacka : VW
 Model : Golf
 Stav tachom.: 56 336



STK : 12. 2010
 Emise : 12. 2010
 Inspekce : 07. 2010

Pred.naprava		Zad. naprava		Vyhodnoceni					
Hodnoty sbihavosti									
 Plus 2,1 mm Ma byt 1,0 - 2,0 mm		 Plus 3,6 mm Ma byt 2,0 - 4,0		Sbih. pr. NE OK Sbih. zad. OK					
 Pred.naprava		 Zadni naprava		 Rucni brzda					
Test brzd 		Leva Dif. % Pedal Prava 284 39 0 173 735 15 0 618 1343 16 0 1128 1942 12 0 1706 2501 10 0 2250 2893 10 0 2603 3590 10 0 3227		Leva Dif. % Pedal Prava 147 25 0 196 183 28 0 255 190 29 0 264 222 31 0 323 231 36 0 362 253 37 0 402 352 37 0 559		Leva Dif. % Pedal Prava 215 31 0 147 725 31 0 500 833 35 0 541 971 37 0 611 1089 42 0 631 1236 44 0 692 1716 45 0 943			
						Soumernost pred. OK Soumernost zad. NE OK Soumernost ruc. MEZNI			
Celkova brzdn.sila Zpomaleni (ma byt min.) Nozni brzda		7 828 N >= 50%		2 659 N >= 16%		Brzdovy test OK			
Brzdn.sila rozdeleni		88%		12%					
Váha vozidla				Celkova váha 1100 kg					
Podvozek 		Leva Amplituda Prava 37 1. 35 42 2. 41 25 3. 23		Leva Amplituda Prava XX 1. XX XX 2. XX XX 3. XX		Leva Amplituda Prava 11 1. 11 05 2. 06 00 3. 01		Podvozek prezkousen	
								■ Levá ■ Prava	

Závady!



Vyruk - upevneni
Manzeta nahonu
Baterie
Brzd.obloz.zadni

Rizeni vule
Svetlomety stav
Motor ztrata oleje



Pred. pneu profil pod 1,6 mm
Zad.pneu profil pod 2,0 mm

Pneumatiky zakoupene u nas v dubnu a kvetnu vyvazime a prezujeme zdarma
 K motorovemu oleji CASTROL GTX olejovy filtr zdarma!

Dekujeme za navstevu naseho servisu a prejeme Vam mnoho statnych kilometru.